03500.014241



PATENT (

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:		)	
		:	Examiner: Brian K. Talbot
NOBUHIRO ITO		)	
		:	Art Unit: 1762
Appln. No.: 09/505,627		)	
		:	
Filed: February 16, 2000		)	
		:	
For:	MANUFACTURING METHOD OF	)	
	ELECTRON BEAM APPARATUS AND	:	
	SPACER, AND ELECTRON BEAM	)	
	APPARATUS	:	
		)	
U.S. Patent No.: 7,067,171 B2		:	
		)	
Issued:	June 27, 2006	:	November 16, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

## CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors that appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

11/20/2006 HAHHED1 03000055 7067171 01 FC:1811 100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentee Registration No. 48,512

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

Facsimile: (212) 218-2200

603026v1

### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,067,171 B2

**DATED** 

June 27, 2006

INVENTOR(S) :

NOBUHIRO ITO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 1**

Line 23, """MIM type")." should read --"MIM type").--.

### COLUMN 4

Line 11, "110 Pa." should read --10<sup>-4</sup> Pa.--.

### **COLUMN 13**

Line 23, "nitride" should read --nitrides--..

### COLUMN 14

Line 20, "the" should read --a--.

### COLUMN 17

Line 8, "even the" should read --even if the--.

### COLUMN 20

Line 50, "DX1" should read --Dx1--.

### COLUMN 23

Line 26, "the" (second occurrence) should be deleted.

### **COLUMN 27**

Line 20, "device-" should read --device--.

### MAILING ADDRESS OF SENDER:

PATENT NO. US 7,067,171 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

603026v1

.

NOV 2 1 2006

# Staple Here Only!

## UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,067,171 B2

**DATED** 

June 27, 2006

INVENTOR(S) :

NOBUHIRO ITO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### COLUMN 30

Line 26, "line memory 115" should read --line memory 1705--.

### **COLUMN 36**

Line 8, "trajectory" should read --trajectory,--.

### COLUMN 42

Line 14, "Embodiment I." should read -- Embodiment 1.--.

### COLUMN 43

Line 1, "uAccording" should read --According--; Line 28, "poison" should read --position--; and Line 36, "in" should be deleted.


#### **MAILING ADDRESS OF SENDER:**

PATENT NO. US 7,067,171 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

NOV 2 1 2006



# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,067,171 B2

**DATED** 

June 27, 2006

INVENTOR(S) :

NOBUHIRO ITO

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 1**

Line 23, """MIM type")." should read --"MIM type").--.

### **COLUMN 4**

Line 11, "110 Pa." should read --10<sup>-4</sup> Pa.--.

### **COLUMN 13**

Line 23, "nitride" should read --nitrides--...

### COLUMN 14

Line 20, "the" should read --a--.

### **COLUMN 17**

Line 8, "even the" should read --even if the--.

### COLUMN 20

Line 50, "DX1" should read --Dx1--.

### **COLUMN 23**

Line 26, "the" (second occurrence) should be deleted.

### **COLUMN 27**

Line 20, "device-" should read --device--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile


No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

603026v1

No. of add'l. copies

PATENT NO. US 7,067,171 B2





# Staple Here Only!

### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

PATENT NO. :

7,067,171 B2

**DATED** 

June 27, 2006

INVENTOR(S) :

**NOBUHIRO ITO** 

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

### **COLUMN 30**

Line 26, "line memory 115" should read --line memory 1705--.

### COLUMN 36

Line 8, "trajectory" should read --trajectory,--.

### **COLUMN 42**

Line 14, "Embodiment I." should read -- Embodiment 1.--.

### COLUMN 43

Line 1, "uAccording" should read --According--; Line 28, "poison" should read --position--; and Line 36, "in" should be deleted.

**MAILING ADDRESS OF SENDER:** 

PATENT NO. US 7,067,171 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

NOV 2 1 2006

Form PTO 1050 (Rev. 3-82)

603026v1